

# Ford Triton Spark Plug Thread Repair Kit

## Part No. 38900

### Replacement Parts

393-300  
TAP HSS 3/4-16NF RH STRAIGHT

389-100  
FORD SPARK PLUG INSERT

389-200  
11/16" CORE DRILL

390-400  
SBR RUBBER TUBING 1/4 ID

389-400  
GUIDE, FORD SPK PLUG INSERT IN

370-700  
NEEDLE VALVE

MSI610A  
DVD, INSTRUCTIONAL

560-16  
1/8" POLY BARB CONNECTOR - LEA

389-900  
BLOWCASE, DARK GRAY

390-200  
STOPPER

390-300  
PLUG 1/8" NPTF MALE THREAD

